



Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.




Sign post at Kranji Road opposite Kranji Camp

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.




Sign post at Kranji Road beside Kranji Camp

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.




Sign post at Sungei Kadut northbound

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.




Sign post at Sungei Kadut southbound

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.




Sign post at Stagmont Ring southbound

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.




Sign post at Stagmont Ring northbound

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.




Woodlands Road past temporary bus garage – for northbound

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.




Choa Chu Kang Road south corridor – for northbound

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.




Sign post north side of Gombak Drive

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.




Sign post at Gombak Drive southbound

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.




Sign post at Hillview Drive entrance in old Stanchat Car Park

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.




Sign post at Hillview Drive beside old bridge next to Park Connector sign

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.




Sign post on trackside south end of bridge at Rail Mall

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.




Sign post bottom of path south end of bridge at Rail Mall

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.




Sign post beside road at Bukit Drive (Hindhede) Car Park (beside pavement at end of open drain)

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.



Sign post on trackside north end of bridge at Hindhede

Post to be routed for Sign Boards to be fitted.
Holes in sign board align with holes in post.
Fixing use tight fit wooden dowels hammered in.



Sign post trackside at Bukit Timah Rail Station where driveway meets the track (Near current SLA Sign)